## UNIFABS LTD

## Unifabs Technical Standards - Revision: 01. Dated 07/03/2019

Section	Area	Section	Area
1	Enquiry/Order	4.1.6	When punching holes than the top
1.1	Unless stated, we will use the most cost effective method of manufacture which could be punch or laser cut. If a certain process is detrimental to the part, please advise us at enquiry stage	4.2	Laser Cutting
1.2	Any order given verbally will not be processed until confirmed in writing	4.2.1	Parts cut with coating processed
1.3	Quotations may be produced against samples/templates. However, our interpretation will be forwarded in PDF format to gain written approval before manufacture	4.2.2	Material can only be p
2	CAD & Drawings	4.2.3	Anti spatter may be u
2.1	Unless stated, we will assume drawings are shown in 3rd angle projection	4.2.4	Long components wit build up
2.2	Electronic formats that can be used by Unifabs are; Solidworks (.sldprt, sldasm, slddrw), DWG (.dwg), DXF (.dxf), STEP (.stp, .prt)	4.2.5	Aluminium >3mm is li enquiry stage if this n
2.3	If none of the above formats are available, a design/drawing charge may be applied (this will be stated on our quotation)	4.2.6	Polycoating may become pressure assist gas un face will be mark free
2.4	Where CAD and PDFs are supplied, the CAD file will always be used as the master so, if they are different, this is our customer's responsibility	4.2.7	A small laser tag may inform us at enquiry s
2.5	CAD files must be supplied at 1:1 scale. Where this is not possible, Unifabs must be notified	4.3	Forming/Bending
2.6	Hand drawings can be accepted although our interpretation will be sent for approval, prior to manufacture	4.3.1	Witness/tooling mark
2.7	Unifabs must be made aware of any revisions to drawings, following the enquiry	4.3.2	If handed parts are re
2.8	Any components from brushed material must have the grain direction shown on the drawing	4.3.3	Where holes and slot distort when folded. T needs changing to re
2.9	Any components from tread plate/durbar to have the patterned face identified	4.4	Sawing
2.10	Any patterned or tread plate material must have the patterned face stated on the drawing	4.4.1	We have no control o
2.11	If there is an 'A' Face required, please show this on your drawing	4.4.2	Internal deburring of s required at enquiry st

<ul> <li>4.1.6 When punching holes in material &gt;3mm, the bottom of the hole can be larger than the top</li> <li>4.2 Laser Cutting</li> <li>4.2.1 Parts cut with coating on may leave a slight residue around the cut edge once processed</li> <li>4.2.2 Material can only be profiled with coating on the top face</li> <li>4.2.3 Anti spatter may be used to aide cutting but can leave a slight oily residue</li> <li>4.2.4 Long components with narrow part widths are liable to bow/distort due to heat build up</li> <li>4.2.5 Aluminim &gt;3mm is likely to create a burred cut edge. Please inform us at enquiry stage if this needs removing</li> <li>4.2.6 Polycoating may become detached from small components due to the high pressure assit gas used. If this is the case, we can not guarantee the 'A' face will be mark free</li> <li>4.2.7 A small laser tag may be present on parts. If this needs removing, please inform us at enquiry stage</li> <li>4.3 Forming/Bending</li> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> <li>4.4.1 We have no control of the seam size or position of the seam on box section</li> </ul>	Section	Area
<ul> <li>4.2.1 Parts cut with coating on may leave a slight residue around the cut edge once processed</li> <li>4.2.2 Material can only be profiled with coating on the top face</li> <li>4.2.3 Anti spatter may be used to aide cutting but can leave a slight oily residue</li> <li>4.2.4 Long components with narrow part widths are liable to bow/distort due to heat build up</li> <li>4.2.5 Aluminium &gt;3mm is likely to create a burred cut edge. Please inform us at enquiry stage if this needs removing</li> <li>4.2.6 Polycoating may become detached from small components due to the high pressure assist gas used. If this is the case, we can not guarantee the 'A' face will be mark free</li> <li>4.2.7 Asmall laser tag may be present on parts. If this needs removing, please inform us at enquiry stage</li> <li>4.3 Forming/Bending</li> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.1.6	
<ul> <li>4.2.1 processed</li> <li>4.2.2 Material can only be profiled with coating on the top face</li> <li>4.2.3 Anti spatter may be used to aide cutting but can leave a slight oily residue</li> <li>4.2.4 Long components with narrow part widths are liable to bow/distort due to heat build up</li> <li>4.2.5 Aluminium &gt;3mm is likely to create a burred cut edge. Please inform us at enquiry stage if this needs removing</li> <li>4.2.6 Polycoating may become detached from small components due to the high pressure assist gas used. If this is the case, we can not guarantee the 'A' face will be mark free</li> <li>4.2.7 A small laser tag may be present on parts. If this needs removing, please inform us at enquiry stage</li> <li>4.3 Forming/Bending</li> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.2	Laser Cutting
<ul> <li>4.2.3 Anti spatter may be used to aide cutting but can leave a slight oily residue</li> <li>4.2.4 Long components with narrow part widths are liable to bow/distort due to heat build up</li> <li>4.2.5 Aluminium &gt;3mm is likely to create a burred cut edge. Please inform us at enquiry stage if this needs removing</li> <li>4.2.6 Polycoating may become detached from small components due to the high pressure assist gas used. If this is the case, we can not guarantee the 'A' face will be mark free</li> <li>4.2.7 A small laser tag may be present on parts. If this needs removing, please inform us at enquiry stage</li> <li>4.3 Forming/Bending</li> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.2.1	
<ul> <li>4.2.4 Long components with narrow part widths are liable to bow/distort due to heat build up</li> <li>4.2.5 Aluminium &gt;3mm is likely to create a burred cut edge. Please inform us at enquiry stage if this needs removing</li> <li>4.2.6 Polycoating may become detached from small components due to the high pressure assist gas used. If this is the case, we can not guarantee the 'A' face will be mark free</li> <li>4.2.7 A small laser tag may be present on parts. If this needs removing, please inform us at enquiry stage</li> <li>4.3 Forming/Bending</li> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.2.2	Material can only be profiled with coating on the top face
<ul> <li>4.2.4 build up</li> <li>4.2.5 Aluminium &gt;3mm is likely to create a burred cut edge. Please inform us at enquiry stage if this needs removing</li> <li>4.2.6 Polycoating may become detached from small components due to the high pressure assist gas used. If this is the case, we can not guarantee the 'A' face will be mark free</li> <li>4.2.7 A small laser tag may be present on parts. If this needs removing, please inform us at enquiry stage</li> <li>4.3 Forming/Bending</li> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.2.3	Anti spatter may be used to aide cutting but can leave a slight oily residue
<ul> <li>4.2.5 enquiry stage if this needs removing</li> <li>Polycoating may become detached from small components due to the high pressure assist gas used. If this is the case, we can not guarantee the 'A' face will be mark free</li> <li>4.2.7 A small laser tag may be present on parts. If this needs removing, please inform us at enquiry stage</li> <li><b>4.3 Forming/Bending</b></li> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li><b>4.4 Sawing</b></li> </ul>	4.2.4	
<ul> <li>4.2.6 pressure assist gas used. If this is the case, we can not guarantee the 'A' face will be mark free</li> <li>4.2.7 A small laser tag may be present on parts. If this needs removing, please inform us at enquiry stage</li> <li>4.3 Forming/Bending</li> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.2.5	
<ul> <li>4.2.7 inform us at enquiry stage</li> <li>4.3 Forming/Bending</li> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.2.6	pressure assist gas used. If this is the case, we can not guarantee the 'A'
<ul> <li>4.3.1 Witness/tooling marks may be visible</li> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.2.7	
<ul> <li>4.3.2 If handed parts are required, please inform us of any 'A' face required</li> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.3	Forming/Bending
<ul> <li>4.3.3 Where holes and slots are positioned near to bend lines they can pull or distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.3.1	Witness/tooling marks may be visible
<ul> <li>4.3.3 distort when folded. This is our customer's responsibility and, if the design needs changing to reduce this, may incurr extra cost</li> <li>4.4 Sawing</li> </ul>	4.3.2	If handed parts are required, please inform us of any 'A' face required
	4.3.3	distort when folded. This is our customer's responsibility and, if the design
4.4.1 We have no control of the seam size or position of the seam on box section	4.4	Sawing
	4.4.1	We have no control of the seam size or position of the seam on box section

Standard Tolerances, Unless Stated						
Process	Size	Tolerance +/-				
Laser Cutting	all	0.25mm				
Punching	all	0.25mm				
Folding	<2000mm	0.5mm				
Folding	>2000mm	0.75mm				
Drill-Dia	dependent	0.5mm				
Drill-Position	all	0.75mm				
Welding	<1000mm	0.5mm				
Welding	1000-2000mm	1.0mm				
Welding	>2000mm	job dependent				

If there is an 'A' Face required, please show this on your drawing	4.4.2	Internal deburring of sawn box section is not standard. Please advise if this is required at enquiry stage	
Material	4.5	Drilling, tapping and countersinking	
	4.5.1	The above operations may create a raised burr	
	4.5.2	when countersinking, we will work to the top countersink size and the bottom hole size will be generated from this	
	4.5.3	Cutting fluid is used to assist and may be present on parts	
	4.6	Welding	
Where possible, we would like 24 hours notice of any incoming deliveries	4.6.1	Unless stated, we will use what we believe to be the best method of welding (MIG or TIG) and weld lengths, tacks etc	
Deliveries of material must not exceed 1tonne packs	4.6.2	If there are areas that require no weld to be present, we must be made aware of this	
We can not process free issue material smaller than 1m square	4.6.3	Our welders are NOT coded. If there is any specific requirement, please let us know	
	4.6.4	Spatter may be present on finished parts	
	5	Packaging	
	5.1	All goods will be packaged to our standard levels. If you have a specific packaging request or would like to know more, please let us know at enquiry stage	
Processing	6	Documentation	
Punch	6.1	Where mill certification or material testing is required, please let us know to what level and your need of this at enquiry stage as there may be cost implications	
	7	Inspection	
Sharp edges created by the punching process will be present	7.1	We carry out standard process checks to our own internal levels. If anything specific is required, please make us aware at enquiry stage as there may be cost implications	
	8	Powder Coating	
the punching process does mark the back face of the material. Please advise if an 'A' face is required	8.1	Our inline pre treatment is 3 stage and comprises of phosphate degrease and 2xrinse processes	
Witness marks from the punch tools may be visible	8.2	If items are too large to be track hung, we will process manually and cure in a box oven. In this instance, items would be hand cleaned prior to powder coating	
	face and will remain on the component. If coating is not needed, please advise us of this at enquiry stage. If coating is removed, we can not be held Stainless and aluminium may be subjected to cross contamination as common tooling/slats are used on laser, punch, pressbrakes, drilling etc All deliveries of free issue material must be accompanied by a delivery note stating the grade, thickness and quantity Where possible, we would like 24 hours notice of any incoming deliveries Deliveries of material must not exceed 1 tonne packs We can not process free issue material smaller than 1m square If poor quality material is supplied (rusty, marked etc) this will be processed at your risk and may affect the final finish of a product. Rust can also hinder the cut quality of laser cut parts Free issue material is processed at the Customers risk and Unifabs will only be held liable for processing costs Material will only be held for 30 days following order completion. If material is required to be delivered back, this may incurr additional delivery charges <b>Processing</b> A 0.5mm tag will be present. If this needs removing, please inform us at enquiry stage Sharp edges created by the punching process will be present De-burring is not included in prices as standard. If this is required, please make us aware at quotation stage	Material       4.5         All care will be taken to protect both faces of material, however, due to processing, some marks/blemishes may be visible       4.5.1         Stainless and aluminium will generally be processed with coating on one face and will remain on the component. If coating is not needed, please advise us of this at enquiry stage. If coating is removed, we can not be held       4.5.2         Stainless and aluminium may be subjected to cross contamination as common tooling/slats are used on laser, punch, pressbrakes, drilling etc       4.5.3         All deliveries of free issue material must be accompanied by a delivery note stating the grade, thickness and quantity       4.6         Where possible, we would like 24 hours notice of any incoming deliveries       4.6.1         Deliveries of material must not exceed 1tonne packs       4.6.2         We can not process free issue material smaller than 1m square       4.6.4         If poor quality material is supplied (rusty, marked etc) this will be processed at the cut quality of laser cut parts       5.1         Free issue material is processed at the Customers risk and Unifabs will only be held for 30 days following order completion. If material is required to be delivered back, this may incurr additional delivery charges       5.1         Processing       6       7         All deliveries created by the punching process will be present       7.1         De-burring is not included in prices as standard. If this is required, please mark us avere at quotaton stage       8	11 there is an A Pack required, please show this on your usawing       14.42       required at enquiry stage         Material       4.5       Drilling, tapping and countersinking         All care will be taken to protect both faces of material, however, due to processing, some marks/blemshes may be visible       4.5.1       The above operations may create a raised burr         Stainless and automitum will generated to this at enquiry stage. If coating is not needed, please advise us of this at enquiry stage. If coating is not needed, please advise us of this at enquiry stage. If coating is not needed, please advise us of this at enquiry stage. If coating is not needed, please advise us of this at enquiry stage. If coating is not needed is especial advise us of this at enquiry stage. If coating is not needed is especial advise us of this at enquiry stage. If coating is not needed is especial advise us of this at enquiry stage. If coating is not needed is especial advise us of this at enquiry stage. If coating is not needed we can not be held         Stainless and advisition will go expected to cross contamination as common tooling/sista are used on taser, purch, pressbrietes, offilling etc.       4.6.1       Unless stated, we will use the assist and may be present on parts         All deliveries of metrial must not exceed 10nne packs       4.6.2       If there are areas that require no weld to be present, we must be made aware of this at enquiry advised the final finish of a product. Rust can also hinder at your risk and may affect the final finish of a product. Rust can also hinder advise advise advise or parts       4.6.3       Spatter may be present on finished parts         Frecessing       5       Pa

1